### **APPLICATION**

#### FOR

### UNITED STATES LETTERS PATENT

## PATENT APPLICATION

# **SPECIFICATION**

#### TO ALL WHOM IT MAY CONCERN:

Be it known that Rajagopalan Srinivasan of 105 Clementi Road, #06-06, Singapore 129789, Anandakrishnan Sundarraman of Plot No. 46, Door No. 4, Bhuvaneshwari Nagar 4th Street, Chromepet, Chennai 600044, India and Pradeep Kumar Viswanathan of #2, 'Anubav', 12 Valluvar Road Extension, Jagannatha Nagar, Arumbakkam, Chennai 600106, India, have invented certain improvements in METHOD AND APPARATUS FOR MANAGING PROCESS TRANSITIONS of which the following description is a specification.

PS/NUS14.CVR

5



### METHOD AND APPARATUS FOR MANAGING PROCESS TRANSITIONS

#### Reference To Pending Prior Patent Application

This patent application claims benefit of pending prior U.S. Provisional Patent Application Serial No. 60/248,402, filed 11/14/2000 by Rajagopalan Srinivasan et al. for METHODS AND APPARATUS FOR MANAGING PROCESS TRANSITIONS (Attorney's Docket No. NUS-14 PROV), which patent application is hereby incorporated herein by reference.

#### Field Of The Invention

This invention is directed to a method and apparatus for aiding operators and computer programs in managing process transitions during the operation of a complex process facility such as a chemical process plant, nuclear power plant, and semiconductor manufacturing facility. Examples of transitions that commonly occur in plants include, but are not restricted to, startup or shutdown of the plant, switching

The state of the s

15

5

of a unit from a normal operation state to a different state for the purpose of maintenance or regeneration, variations made in the operating conditions to accommodate feed grade changes in a plant, variations made in the operating conditions to accommodate product slate changes in a plant, etc. Examples of computer programs that would be aided by the apparatus in this invention include, but are not restricted to, regulatory and supervisory controllers, alarm generation and management systems, advanced control systems, fault diagnosis systems, etc. Also this invention describes a method and system for monitoring processes during transitions, which identifies abnormalities and informs the plant operator regarding the same. Since none of the existing monitoring techniques can be used for monitoring transitions and since the probability of fault is higher during transitions than at steady state, such a system would be of immense help to operators.

The party from the course from the man of the course of th

15

20

### Background Of The Invention

The operation of a complex process facility requires the assimilation of a large amount of data generated frequently from sensors, inferring the state of the process from these data and executing regulatory and supervisory actions to ensure safety and efficiency. While much of the operation of the modern complex process facility is automatically controlled, the execution of the process during transitions requires extensive human intervention and supervision. These operator interventions during transitions include starting or stopping process units such as pumps and compressors, disabling or enabling controllers, and reconfiguring units and controllers with different parameter settings. Transitions result in substantial changes in the values of one or more process variables. During transitions, some of these plant variables may therefore take values substantially different and outside their normal, Because of the large changes and steady state range. the unusual values of the process variables, plant

15

5

computer programs that are configured for only one operating condition generate incorrect results. One example of this is the alarm system that would generate spurious alarms if it were not specifically configured for the transition. Other such computer programs include those for advanced control, unit optimization, etc. Operators therefore disable and/or ignore the results of such plant computer programs during transitions. The operator actions, mentioned above, that bring about a transition have to be performed at a specified time dependent on the status and conditions of the plant. Failure in this can lead to abnormal situations.

D. H. Hwang and C. Han, "Real-time Monitoring For A Process With Multiple Operating Modes", Control Engineering Practice, 7, 891-901, 1999, proposed a statistical method for monitoring processes with multiple operating modes. Their technique is applicable only for operation modes a that share common characteristics and do not introduce a significant amount of nonlinearities in the process

15

5

1

behavior. Many common transitions such as a cold startup of a reactor or distillation column, decoking of a furnace, swinging of units for product or feed grade changes, and others result in significant nonlinear changes and cannot be monitored by their approach.

Process transitions are typically carried out by operators by following a standard operating procedure.

A few techniques exist for monitoring the execution of the operating procedures in a process plant.

A method suggested in U.S. Patent No. 5,511,004, issued April, 1996 to Dubost et al., establishes a reference state and a current state for an industrial evolutionary process from physical parameters measured on all the equipment items employing the evaluating process. These two states are compared, parameter by parameter, by resorting to fuzzy logic for classifying the quantities, and a diagnosis is established using expert rules.

U.S. Patent No. 5,070,468, issued December, 1991 to Niinomi et al., presents a fault diagnosis system.

15

5

The normal range of process data is stored in the system and is employed for online comparison to determine if the process is normal or not. Patterns exhibited by the process variables for different fault patterns are detected and recorded in the system.

When a fault is identified, the pattern is compared with this stored database and the fault is diagnosed.

U.S. Patent No. 5,392,320, issued February, 1995 to Chao et al., provides a monitoring system for a core of the nuclear reactor. Some process variables that need to be continuously monitored are identified. A database is maintained for normal and abnormal operation. Comparison of online data is done with this database to identify the plant situation.

An approach to monitoring a transient is described in U.S. Patent No. 4,678,622, issued July, 1987 to Rowe et al. This makes use of the known phenomenon that during the startup in a nuclear reactor, the neutron density increases. However, there could also be an increase in the neutron density due to some abnormality. A system is built to detect

The same sum of the same sum o

15

5

the abnormality. If the startup is done normally, the neutron density increases slowly, whereas if there is a fault, there is an exponential increase. This difference is used for identifying the fault during startup.

A method and apparatus for fault diagnosis is described in U.S. Patent No. 5,099,436, issued March, 1992 to McCown et al. In this system, the online values of variables are continuously monitored. If there is any deviation from normal, it is mapped to any pre-trained event (fault). It also consists of a symptom-fault model that can determine the cause of the failure.

U.S. Patent No. 5,023,045, issued June, 1991 to Watanabe et al., describes a neural network based technique for detecting malfunctions in plants. The neural network is trained with normal and different runs of data with malfunctions. So this system, when used with online run, can identify trained malfunctions. An application on a nuclear power station has been discussed. Since this application

20

5

requires training, it can function only for known faults for which the network has been trained.

A few other techniques also exist for monitoring the operating procedures for nuclear and thermal power plants. However, all of these techniques employ raw sensor values in their analysis.

There exist some techniques in published literature which use signed directed graphs (see Iri, M., Aoki, K., O'Shima, E. and Matsuyama, H., "An Algorithm For Diagnosis Of System Failures In Chemical Processes", Computers and Chemical Engineering, 3, 489-493, 1979) and trends (see Rengaswamy, R. and Venkatasubramanian, V., "A Syntactic Pattern Recognition Approach For Process Monitoring And Fault Diagnosis", Engineering Applications Of Artificial Intelligence, 8(1), 35-51, 1995; Vedam, H. and Venkatasubramanian, V., "A Wavelet Theory Based Adaptive Trend Analysis System For Process Fault Diagnosis", Proceedings Of The American Control Conference, 309-313, 1997) for monitoring steady state processes. During process transitions, the process is

NUS-14

The second state of the se

5

in a dynamic state and variable profiles change significantly. For monitoring such process behavior, none of the existing techniques (such as neural networks, signed directed graph or trend-based methods) could be used.

First, consider a signed digraph based technique. During process transitions, since interactions between the different variables vary with process operating conditions and time, a general cause-effect relation between process variables could not be obtained. So signed digraph based techniques cannot be used for monitoring process transitions.

In the trend-based approaches, the evolution of a process variable is classified based on its shape into slowly increasing, drastically increasing, constant, etc., by calculating the second order derivatives of the process variables. These are termed as second-order trends. First order derivatives of process variables result in trends which are classified into increasing, decreasing and constant. These are termed as first-order trends. Neither the second-order nor

20

20

15

the first-order trend-based approaches can be applied to monitor process transitions as described below. As an example, consider the transition "startup of a reactor" that is performed in three main phases: (1) charging of reactants at room temperature (30° C) into the reactor, (2) ramping up the temperature from 30° C to 75° C over 1.5 hours, and (3) maintaining the temperature at 75° C. Each process variable could display different trends during different phases. temperature sensor in the above example would display a constant trend in phase 1, an increasing trend in phase 2, and a constant trend again in phase 3. Existing trend-based approaches are designed for fault detection in steady state operation and map a fixed trend (such as increasing temperature) occurring at any time with a fixed process state (such as a runaway reaction). This can lead to wrong results when used to monitor process transitions. In the above example, while the increasing trend in temperature would be diagnosed correctly as due to a runaway reaction if the process is in phase 3, an increasing trend in the

NUS-14

15

5

same temperature variable during phase 2 would be misdiagnosed as due to a runaway reaction. Due to this and other limitations discussed later, existing trend based techniques can not be applied for monitoring transitions.

### Summary Of The Invention

It is an overall object of this invention to provide a method and apparatus for aiding operators and plant computer programs in managing a process when it undergoes transitions.

It is a more specific object of the invention to aid the operator of a complex process facility by providing a computer-based system and a method of operation which incorporate prior generated knowledge of the process operation along with on-line plant data, whereby to identify the current state of the plant and monitor the plant during transitions.

It is a further object of the invention to provide such a system and method of operation which simultaneously provide the operator and other plant

computer programs with information concerning the current state of a process, section or subsection and other useful, context-sensitive facts such as bounds on the process variables and expected and observed trends of these variables, steps in the transition which have been completed earlier, and steps in the transition which should be executed next.

This apparatus enables some plant computer programs to be robust to operating mode changes and reconfigure themselves to operate effectively during different process transitions and across multiple plant operating modes.

It is an additional object of the invention to provide a system and method of operation, which generates a permanent record of appropriate system and process conditions at important moments of each transition including its start, its completion, when something is abnormal, the operator actions, their magnitude, timing and sequence, etc. This record can be queried to provide decision support for plant operations and other activities that would gain by the

20

5

<u>L</u>dr

|4 |13

of the first first transfer and transfer to the first transfer and transfer transfer and transfer transfe

H

15

5

knowledge of the transitions. An example of decision support includes a list of transitions in the record similar to a fully or partially specified one, the process conditions during those, operator actions, etc.

It is an additional object of this invention to provide a system and method for tracking and monitoring processes during transitions. Transitions are typically carried out by operators by following a set of standard operating procedures. The main challenge in monitoring transitions is run-to-run deviations. A technique is presented here which can identify the current state of the operating plant during a transition and perform context sensitive monitoring. If any deviation from normal operation is observed, the system flags the abnormality to the operator for necessary recovery of the process.

Briefly, the present invention includes a new method and apparatus for developing a generic facility for the management of process transitions. The apparatus employs a method for offline

The state of the s

5

characterization of process plant and generation of a comprehensive knowledge base, which is deployed for real time mode-transition identification. Once the current plant state is identified, other subscribing applications are notified regarding the same.

The apparatus also includes a method for monitoring transitions (startup, shutdown, grade changes, etc.) in complex processes. Since trends alone are not sufficient for monitoring transitions, we have developed a technique called enhanced trends that include the process variable magnitude and the trend duration along with trend. The algorithm described employs a preprocessing technique to obtain process trends in addition to the quantitative information from the plant. The dictionary of possible transitions for each plant section is generated offline from the plant history data and stored corresponding to each sensor. The algorithm cannot only point out the region in the plant where an abnormality has occurred, but can also further resolve it to the level of a sensor.

20

The state that the state and t

15

5

The apparatus also includes a method that allows for run-to-run variations during process transitions.

A dynamic feature synchronization algorithm is employed to synchronize profiles from different runs. After synchronization, comparison of the expected trend and observed trend is done by using a comparison algorithm. Since transitions are usually performed by following a set of operating procedures, this knowledge is also made available to the system using a Grafcet representation. If any fault is identified by the system, the details of the fault, as well as the current task in the operating procedure during which the fault is identified, is informed to the operator.

#### Brief Description Of The Drawings

Fig 1. is a schematic diagram of the overview of the invention;

Fig. 2 is a schematic diagram of the method for hierarchically dividing the plant into sections and subsections;

20

5

Fig. 3 shows how a process variable can be divided into periods of modes and transitions based on the changes in the variable value;

Fig. 4 shows the decision-making sequence followed by methods for identifying if a subsection is in a mode or transition;

Fig. 5 shows the process knowledge base generation technique;

Fig. 6 shows a schematic of the method for transition identification;

Fig. 7 shows the Grafcet representation for a startup procedure for a distillation column;

Fig. 8 shows the technique for comparing the different elements of an enhanced trend; and

Fig. 9 shows a typical trend during different runs of a process transition.

### Detailed Description Of The Preferred Embodiments

The invention will now be described in the context of a chemical process plant, but it should be realized that it has application to a wide variety of

NUS-14

<u>k</u>nb ĽÍ

5

15

20

complex process facilities such as, for example, pharmaceutical operations, semiconductor and microelectronics manufacturing, specialty chemicals, paper and pulp mills, power plants, etc. Any chemical plant is instrumented with numerous

sensors that monitor various plant variables such as temperatures, flow rates, pressures, etc. The signals generated by the sensors are fed to the plant distributed control system (DCS) that performs and coordinates regulatory control of some of the variables. These variable values are also displayed to operators through monitors in the control room. Some of these values are also used by other plant computer programs such as an alarm system, a unit optimization system, etc., which help the operator to run the process safely and efficiently. During large periods of time, the plant is typically operated near one or more steady state conditions. During such a steady state condition, most process variables will vary slightly due to noise and disturbances. variations would be within a narrow range around the

fixed steady state value. However, not infrequently, the plant (or one of its constituent sections or subsections) will undergo a transition aimed at moving it from one steady state to another. Transitions are normally executed by plant operators who follow previously defined procedures to start or stop process units, controllers and instrumentation, or to reconfigure them with different settings so that the plant settles down to a different steady state. Many plant computer programs are configured solely for steady state operations and do not function satisfactorily during such transitions. Operators therefore disable them, or ignore or override their results, during the transitions.

15

currently found in a typical chemical plant. The present invention provides a system that provides context-sensitive information and guidance to the operator during the transitions and automatically reconfigures other plant computer programs. Examples of automatic reconfiguration include the turning

All of what has been described so far is

The same time when the many times the party and the party

15

5

on/off of various computer programs, changing parameter settings, etc. An overview of this scheme is presented in Fig. 1. As shown in Fig. 1, the supervisory method identifies the current operating state of the plant. This information is provided to other clients such as alarm management systems, fault detection and diagnosis systems, etc., which configure themselves according the current plant state.

The purpose of the apparatus is fourfold:

- to assess the current state of the process, including the current mode of the process, or the transition being executed;
- 2. to provide the process state and any necessary information to the plant operator and/or plant computer programs;
- 3. to monitor the process for the normal execution of a transition; and
- 4. to continuously track the execution of operating procedure during transition and inform the plant operator of the successful completion of the same.

ML THE RESERVE THE 協 ens (ne

5

20

15

First, there is a way for hierarchically decomposing the process and variables into a number of sections and subsections. When doing this, it is recommended that one use the process flow diagram (or at least a sketch of its physical arrangement) as well as the placement of the sensors. Each section can further be subdivided into one or more sections and/or subsections, and so on. Each subsection comprises of a set of one or more process variables whose values are measured periodically. A change in the value of any of these variables would indicate that the corresponding subsection is undergoing some change.

A plant can be decomposed into one or more sections. For example, a refinery could be divided into a crude distillation unit, a vacuum distillation unit, a catalytic cracking unit, etc., that are called This division is based on a number of sections. factors including the functions and purpose of the major units, their interactions and interconnections, the extent of mutual dependence during their operations, their physical location, etc.

5

15

20

section can be further divided such that it contains at least one sections or subsection. A subsection comprises of one or more sensors (also called variable tags) and performs a supporting function to its parent section. In the above example, the catalytic cracking unit section can be subdivided into a reactor-regenerator subsection, a feed preheater subsection, a main fractionator section, etc. The main fractionator section in turn is decomposed into an overhead subsection, a bottoms subsection and the column subsection. This hierarchical decomposition scheme is depicted in Fig. 2.

Next, there is a way of classifying the state of a subsection or section into modes and transitions as shown in Fig. 3. A subsection is said to be in a mode if, and only if, the values of all the variables with the subsection lie within a narrow range. The modes of subsections can be classified based on the nature of the changes in the process variables into a steady mode, oscillatory mode. A subsection is defined to be undergoing a transition if any of the variables with

20

15

the subsection varies significantly. Transitions of subsections can be classified as sharp transitions, upset transitions, slow drift transitions, desired transitions, etc. A section is said to be in a mode if, and only if, all its subsections are all in modes. A section is said to be undergoing a transition if any of its immediate subsections are in a transition. Each subsection or section will, at any time, be in exactly one of several possible modes or transitions.

Next, a mode of a subsection can be characterized by specifying key descriptors such as an upper and lower bound for each process variable in the subgroup within which that variable would vary if the subgroup is in that mode. A non-empty subset (i.e., at least one) of process variables in a subsection would undergo significant changes when the subsection undergoes a transition. This subset of variables is called the set of key variables for that particular transition. A transition in a subsection is characterized by descriptors such as the subset of key variables along with distinct features in their

The first two also gets to the control of the contr

15

5

variation as the transition is executed, the mode of the subsection immediately prior to the beginning of the transition, the mode of the subsection immediately after the completion of the transition, the start time of the transition and the end time of the transition, etc. The distinct features of the key variables include the sequence of trends, the duration for which each trend persists, variable values at the beginning and termination of each trend, the maximum and minimum values of the variables within the transition, etc.

As mentioned earlier, a section is said to be in a mode if each of its constituent subsections are themselves in a mode. The mode of a section is characterized by the values of the mode of its constituent sections and subsections. A section is said to be in a transition if even one of its constituent sections and subsections undergoes a transition. The transition of a section is characterized by the state (mode or transition) of each of its constituent sections and subsections, and this information may be recorded in a look up table.

15

5

The section's characterization therefore includes this lookup table.

A self-contained knowledge base that contains all the information required for managing process transitions can be developed. The knowledge base of the apparatus comprises of the following constituents:

- an hierarchical description of the process into sections and subsections as described above;
- a list of modes and transitions for each of the process sections and subsections as described above;
- the classification and characterization of each mode as described above; and
- 4. the classification and characterization of each transition as described above.

The above-described knowledge base can be completely developed using the aforementioned method for the plant's hierarchical decomposition, followed by including the list of modes and transitions, followed by characterizing each mode and transition. This knowledge base can be developed in one step or

developed incrementally by following the same methods and appending new sections, subsections, modes and their characterization, transitions and their characterizations, etc.

5

The state

(I)

∭0 ∭ The list of modes and transitions and their characterizations can be developed using the knowledge about the plant and its operation.

Alternatively, if historical data from the plant operation is available, the list of modes and transitions and their characterizations can be developed using the following method.

There is a method for generating the list of modes and transitions for every subsection, section and plant if process historical data is available for every tag. This method is as shown in Fig. 4 and is based on dividing the plant historical data into regions of modes and transitions, using the prior developed description of the process hierarchical decomposition. This method also requires other selected process information including limits for each tag andpre-specified values for tuning parameters.

20

N hil a; È Į, 

5

[][0 15

20

The limits required include the maximum and the minimum value that can be reported by the transmitter for each tag, the transmitter range for each tag, etc. The pre-specified tuning parameters include a threshold for each tag. This threshold is defined to be the maximum allowable variation within a window for constancy and is typically selected to be a small percentage (~5%) of the transmitter range.

Once plant tags have been hierarchically grouped into sections as described above, they can be used for identifying subsection modes and transitions. historical data corresponding to the tags is used in the analysis. Trends can be generated for each tag using any method including, but not restricted to, the wavelet-based trend generation algorithm reported by Vedam, H. and Venkatasubramanian, V., "A Wavelet Theory Based Adaptive Trend Analysis System For Process Fault Diagnosis", Proceedings Of The American Control Conference, 309-313, 1997. Wavelet approximation coefficients at multiple levels are also generated for each tag. A multitude of other wavelets

5

15

20

including the Haar wavelet can be employed for this purpose. Portions of the historical data for which the variable shows a constant trend are identified using the trend information generated earlier. portions are marked as modes for that tag. The mode information generated for all the tags in the subsection is matched to obtain the portions where all of the variables in the subsection remain nearly These portions are identified as the modes for that subsection. Modes are characterized by the maximum and minimum values of each tag within the portion. The mode information for the subsection generated above is then analyzed for duplicate modes. Two modes of a section,  $M_1$  and  $M_2$ , are considered to be the same if their characterizations are essentially similar. A multitude of similarity metrics can be used to compare the characterization of two modes. one such metric, two modes of a subsection,  $M_1$  and  $M_2$ , are said to be the same if the shortest distance between the maximum (or minimum) value of a tag during  $M_1$  is no further from the minimum (or maximum) value of

15

5

the tag during M<sub>2</sub> than a small pre-specified threshold. A typical value for this threshold is 5% of the tag's transmitter range. The similarity measure described above can be replaced with other similarity metrics. If consecutive duplicate modes are encountered, they are merged together to produce a single mode. modes are also checked for their duration, and modes shorter than a pre-specified duration are eliminated by merging these portions along with the transition. After the modes have been identified as described above, the remaining portions of the historical data that have not been marked as modes are now marked as transitions. Key variables are then identified for each transition as described above. Transitions are then characterized using the distinct features in the key variables including the sequence of trends, the duration for which each trend persists, variable values at the beginning and termination of each trend, maximum and minimum values of the variable within the transition, etc., as described earlier.

20

5

The modes and transition characterizations generated above are used to create an event list consisting of all the events - mode or transition for a subsection. The events for sections and plants are inferred from the events of the subsections of which it is comprised. An event look-up table is generated for each section and comprises each of the different combinations of events of subsections and the corresponding event for the section. The entire event look-up table, or any selected consistent subset such as those combinations of subsection events that were observed in historical data, can be used. the above described method, the list of modes and transitions and the characterizations for each mode and transition can be generated from process history data.

Next, there is a method for identifying the current process state. The apparatus implements a method for identifying the current state of the process and each section and subsection and it uses the knowledge base generated from the historical data.

NUS-14

5

The steps in on-line identification of the state of the process are shown in Fig. 5. The method takes as input:

- the knowledge base previously generated for the process;
  - 2. the current values of process variables; and
- 3. values for tuning parameters selected by user.

The knowledge base generated offline is imported for use by the method to identify the current process state. Initialization calculations are performed and user-supplied tuning constants are assigned. The sensor data for all the plant tags sent from the DCS is separated based on the basis of plant groupings. For each subsection, the current sensor data is compared with the knowledge base of the modes possible for that group. If the value of each variable belonging to the subsection falls within the upper and lower limits for a given mode, the subsection is identified to be in that mode. To avoid false signals of a mode, the method waits for a certain minimum

duration for which the subsection remains in the given

15

5

mode before the current mode information is signaled. A user-defined parameter is employed to determine this minimum duration and could take any positive integer value. This procedure is repeated for all the subsections. If the subsection is not identified to be in any of the modes from the knowledge base, but all variables in that subsection are varying within user defined narrow bounds, then the subsection is said to be in an unknown mode. If even one of the variables in the subsection is varying beyond its bounds, the subsection is said to be in a transition.

The current transition is identified using the procedure described in Fig. 6. This procedure compares the currently evolving transition with the transitions existing in the imported knowledge base. The current transition can be identified using a similarity metric to compare its characterization with the characterizations of the transitions in the knowledge base. A multitude of similarity metrics can be used to compare the characterization of the current

5

20

15

transition with that of a transition in the knowledge In one such metric, wavelet decomposition of the plant sensor is carried out for each variable in a subsection undergoing the transition to obtain approximation coefficients for as many levels as is necessary. The number of levels of decomposition is a user-defined parameter and typically takes a value of These wavelet coefficients are then between 1 and 5. compared with the wavelet coefficients for transitions available in the knowledge base. Since the previous mode is known, the comparison can be restricted to only those transitions that are known to occur from this mode. A norm of the difference between the wavelet coefficients is obtained at each level, and a sum of all these norms is computed. The transition that provides the least norm is flagged as the current transition if the value of the norm is smaller than a user defined parameter. If the value of the smallest norm is larger than this user defined parameter, than the transition is flagged as an unknown transition. This procedure is repeated for each subsection that is

5

currently undergoing a transition. The similarity measure described above can be replaced with other similarity measures.

Based on the events identified for the subsections, the event for the sections is inferred by looking-up the event lookup table available in the knowledge base for each section. This procedure is carried out for all the sections by moving up the plant hierarchy.

Thus, the above-mentioned method identifies and tracks the process by identifying the current state - mode or transition.

The transition in a process consists of several phases as mentioned earlier. In addition to tracking the current state of the process, an additional method exists to track the process within the transition. This method takes as its inputs:

a knowledge of the common operating policies
 for the plant, commonly available in the form of
 standard operating procedure of the transition; and

20

5

the distinct features of the process variables during the transition.

The phases in the operation or the standard operating procedure is represented schematically using a Grafcet representation as shown by Viswanathan, S., Johnsson, S. C., Srinivasan, R., Venkatasubramanian, V. and Arzen, K. F., "Automating Operating Procedure Synthesis For Batch Processes: Part I.", Knowledge Representation And Planning Framework, Computers And Chemical Engineering, 22 (11), 1673-1685, 1998. The actions to be performed are represented by Grafcet steps, and the condition for the end of each task is represented using a Grafcet transition. For example, consider the startup of a distillation column, which consists of the following steps:

- 1. initially put all the controllers in manual;
- 2. open the cooling water to the condenser;
- 3. fill liquid of higher bottom product composition in the reboiler and start the reboiler heating, and operate the column in full reflux;

NUS-14

5

- 4. when the product starts collecting in the top and when the tray temperatures remain constant, start the feed pump and operate the column under constant reflux; and
- when the column temperatures remain constant, then the column has reached steady state.

The Grafcet representation for this particular example is given in Figure 7.

For the purpose of tracking and subsequent monitoring of transition, a subset of the distinct features of a process variable (including variable trend, duration of trend and variable value at the beginning and end of the trend) is termed an atom. The series of this atom for a process variable is termed the enhanced trend of that process variable. This information for every process variable during the current transition is obtained from the previously generated knowledge base and is termed as the dictionary of that variable. Portions of the enhanced trend corresponding to each phase in the operating procedure (represented by a Grafcet step) are stored

corresponding to its Grafcet step. Thus, every atom

5

Series in the series of the se

15

20

in the dictionary has a corresponding Grafcet step to which it belongs.

The method for tracking the process within a transition continuously looks at the trend of the evolving process variable. The combination of

variable trend, duration of trend, and variable value at the beginning and end of the trend for a real-time process variable is termed a real-time atom. The logic behind the tracking method is that, there could be minor deviations in the magnitude of the process variable and the start and end time of different phases, but the trend of the process variable should essentially follow the trend as given in the

A dynamic feature synchronization algorithm for this tracking is shown in Fig. 8. As shown in Fig. 8, the algorithm starts with the first real-time atom. A comparison of trend is done with the first dictionary atom. Then for subsequent real-time atoms, the trend is compared with the current dictionary atom and the

dictionary.

next one. If the trend of a real-time atom is equal to the next dictionary atom, then the comparison of the subsequent real-time atoms is done from there; otherwise, for the subsequent real-time atoms, trend is compared with the current dictionary atom. Thus, using this dynamic feature synchronization method, the dictionary atom to which the real-time atom corresponds is identified. Once the dictionary atom is identified, the corresponding phase in the operating procedure, currently being carried out in the plant, can be identified.

This information regarding the current phase of transition may be broadcast to different sections of the plant. This kind of tracking helps in context sensitive process operation and recovery in the case of any abnormality.

The dynamic feature synchronization algorithm described above can be replaced with other equivalent ones such as dynamic time warping. This tracking method is an optional method, which can be used if the

20

5

process current operating phase needs to be identified for a process.

Finally, there exists a method for monitoring This method takes as processes during a transition. input the enhanced trend of the process variables. This method is independent of the Grafcet representation for operating procedures. If the operating procedure information is made available, it may be used. This method essentially consists of a comparison of the different elements of the real-time enhanced trend with that of the dictionary as shown in Fig. 9. For this, the first step is the identification of the dictionary atom to be compared The dynamic feature synchronization algorithm with. discussed above provides this information of the dictionary atom. This tracking method identifies the corresponding dictionary atom for a real-time atom. If the Grafcet information is made available to the system, it additionally provides the phase being performed. As per the flow diagram shown in Fig. 9, first the trend between the real-time and the

NUS-14

5

dictionary atom are compared. If there is a mismatch in trend, it is concluded that there is an abnormality in the process variable, otherwise the comparison proceeds. Then comparison is performed between the process variable magnitude and the trend duration between the real-time and dictionary atom. From this, the matching degree for each process variable is calculated. The degree of fault of the whole process is calculated as a function of degree of fault of individual sensors.

The monitoring method identifies any abnormality during the process transition and informs the operator regarding the same. The details of the sensor (the sensor type, tag name), kind of abnormality (deviation in shape or magnitude or time) and the extent of deviation from normalcy are reported to the operator. This will help the operator rectify and bring the process operation back to normal.

Identification of trend of the process variable is an important step since trend is considered as the main criterion for synchronizing the real-time process

with the dictionary. Both the second-order and the first order trends discussed above can be used for this purpose. Using second-order trends allows for a fine comparison between real time trends and those in the knowledge base where even minor deviations can be detected quickly. On the other hand, the use of first-order trends provides a coarse comparison that is more robust to run-to-run deviations. The method allows for the user to select either the second order or the first order trend based on the how closely the real-time process is required to follow the dictionary.